

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
01	002	010	0000000525	0031.3981 0031.3991	Circuit protection	FBS2	n/a



*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change

The marking on the socket of the fuseholder changes. The new marking includes VDE according IEC with rated voltage and cURus according UL/CSA with rated voltage and rated current.

3 Detailed description of change

Old marking	New marking
FBS VDE 2.5W/10A cURus 250V 10A	FBS2 VDE 250V cURus 250V 10A

Old marking	New marking
	

4 Reason of change

Correction of fuseholder marking.

5 Release date

The change takes effect in ww 35/2015 (Date code 1535 or higher on label).

6 Impact of change and recommended action

Form	No	There are no form changes, only marking adjustments
Fit	No	There are no dimensional changes
Function	No	This is a non-functional change
Production Site	No	There is no change of the production site
Product Label	No	There is no product label change
Customer Action	No	Notification only

7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet FBS2	

FBS2					0118.2292	
creation date	created by	release date	released by	notification no.	revision	page
2015-07-06	dislercy	2015-08-19	dislercy		-	1 of 1